


WIRING DIAGRAM 230 - 240V, 1PH, 50HZ

P/N 9507-029-001A
 50 LB OPL EXPRESS, VF DRIVE
 NO HEAT
 WN0750XA-39_0_X-____-__X

230-240V-1PH-50HZ

WATER VALVES	
H2	- HOT SOAP
H1	- HOT TUB
H3	- HOT TUB
C2	- COLD SOFTENER
C1	- COLD TUB
C3	- COLD TUB



INJECTION SIGNAL CONNECTIONS

P/N 9508-029-001PR
50 LB OPL EXPRESS, VF DRIVE,
NO HEAT

SCHEMATIC

230-240V-1PH-50HZ