


WIRING DIAGRAM 200 - 230V, 1PH, 50HZ

P/N 9507-030-001A
 60 LB OPL EXPRESS, VF DRIVE
 NO HEAT
 WN950X_-39_0_X-_____-__X

230-240V-1PH-50HZ

WATER VALVES	
H2	- HOT SOAP
H1	- HOT TUB
H3	- HOT TUB
C2	- COLD SOFTENER
C1	- COLD TUB
C3	- COLD TUB



SCHEMATIC

230-240V-1PH-50HZ

P/N 9508-030-001PR
 60 LB OPL EXPRESS, VF DRIVE,
 NO HEAT

BUTTONS

INJECTION SIGNAL CONNECTIONS