



DEXTER.
LAUNDRY

DDAD Troubleshooting Inadequate Make Up Air

Inadequate make up air.

- The Dexter DDAD30 stack dryer requires 1.5 sq. ft. or 18" sq. inches of make up air per machine.
- Anything less than the required amount of make up air will effect the performance of the dryer negatively.
- Signs of low make up air, lazy yellow flame in burner, long dry times, over-temp thermostats engaging, low heat in the dryer.

